

BUILDING SAFETY CERTIFICATE

It is certified that the existing building VASHIST PUBLIC SCHOOL situated at V.P.O Behdala, Distt Una(H.P) inspected by the undersigned alongwith concerned Junior Engineer on dated:- 24.01. 2022 is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground +1 st Floor +2 nd Floor	Ground +1 st Floor +2 nd Floor+3 rd floor	----	-----	----	---

It has been observed that no earth quake resistance provision has been adopted for this building and no structure drawing is approved by the competent Govt. certified Engineer which has been produced at the time of inspection and moreover no assistance was taken from Public Works Department for construction of the building.

Hence the structure safety of this building cannot be assured specially from earthquake resistance point of view. This department will not be held responsible for any type of loss of life and property etc. If this structure falls under any circumstances. The year of construction of building is 2012 as certified by the ~~Municipal~~ Pardhan Gram Panchayat Behdala Tehsil and Distt Una. However as per the visual inspection it has been observed that the existing building seems to be safe for running academic sessions 2022-25, as per guidelines issued by the Special Secretary (PW) to the Govt. of H.P notification No. PBW (B) (3)95/2019 dated 13.04.2021. No Officer/official of this department would attend any plea in any Hon`ble Court of law for any type of dispute and claim and loss.

This certificate is only for official use and not for legal purpose

Signature with Seal: _____

[Signature]
Assistant Engineer
Name : Arvind **Una Sub-Division No.II**
H.P.P.W.D.Mehatpur at Dehlan

[Signature]
Designation : **Assistant Engineer**
Name & Address of Department/ Office:
H.P.PWD Una Sub- Division No -II
Mehatpur at Delhan

45
Executive Engineer
Una Division (B&R)
H. P W. D. Una (H.P.)